



Integrate Calcination sheet into Plant sheet

Step by step example:

1. line007c: Kiln operation=yes!
2. line007n: Select method for determining CO₂ emissions from raw material calcination
3. When using method for the first time:
Create corresponding Calcination sheet by pressing a 'Create' button
4. Fill Calcination sheet
5. Manually copy values of **1 or 2 Output data** to Plant sheet Input
6. Change default values in Plant sheet to plant specific data, if available



copy values

Simple Input Method (B1)
No separate Calcination sheet required: Plant specific standard emission factor or CSI default = 525 kg CO₂/t clinker

* Calculation is adjusted according to the selected method for each year individually.

